

VOLUME

4

QUESTION 59

TRANSACTIONS

COMPTES RENDUS

Published by the
international commission
on large dams

Publié par
la commission internationale
des grands barrages

151 Bd Haussmann 75008 Paris, France
Tél. : 764.68.24 - 764.67.33 - 764.54.38
Télex : 641 320 F

NOTE

Units of Measurement

As for the previous Congress and though some authors do not fully agree, we attempt to follow the recommendations of the International System of Units (SI).

For example, hm^3 and km^3 were preferred to 10^6 and $10^9 m^3$, or million and billion cu.m. See Bulletin 34 " ICOLD Guide for the International System of Units (SI) ", page 13.

The decimal sign may be the full stop (Anglo-Saxon usage) or the comma (European usage); but as a safeguard against confusion, full stop (period) and comma are used as decimal sign only.

Where the number of digits before or after the decimal sign exceeds three, the digit should be divided into groups of three by half space.

We meet not enough co-operation from some authors writing in English who go on keeping the comma to separate the groups of three digits instead of using half space. It was not possible to make the appropriate corrections in all the tables provided by the authors and even in the text. Sorry for the inconvenience.

AVERTISSEMENT

Unités de mesures

Comme pour le Congrès précédent et bien que certains auteurs manifestent des réticences à ce sujet, on s'est efforcé de suivre les recommandations du Système International d'Unités (SI).

Par exemple, on a utilisé plus volontiers hm^3 ou km^3 au lieu de $10^6 m^3$ et $10^9 m^3$ ou million et milliard de mètres cubes. Voir Bulletin 34 « Guide CIGB du Système International d'Unités (SI) », page 13.

De même, on a retenu le point (usage anglo-saxon) et la virgule (usage européen) comme signe décimal, mais pour éviter toute confusion, la virgule et le point ne sont utilisés que comme signe décimal.

Aussi, quand le nombre de chiffres avant ou après la virgule est supérieur à 3, les chiffres sont groupés par 3, chaque groupe étant séparé par un court espace.


A ce sujet nous rencontrons encore des difficultés de la part de quelques auteurs de langue anglaise qui continuent à utiliser la virgule au lieu d'un court espace pour séparer les groupes de trois chiffres. Nous n'avons pas pu apporter les corrections nécessaires dans tous les tableaux fournis par les auteurs et même dans le texte. On voudra bien nous en excuser.

TABLE OF CONTENTS

	PAGE
Wording of Question 59	VIII
Table of Contents of Papers on Question 59	IX
Papers on Question 59	I
General Report Question 59	929

TABLE DES MATIÈRES

	PAGE
Libellé de la Question 59	VIII
Table des Matières des Rapports sur la Question 59	IX
Rapports sur la Question 59	I
Rapport Général sur la Question 59	929



PAPERS ON Q 59

RAPPORTS SUR LA Q 59

QUESTION

59

Rehabilitation of dam to ensure safety

Subject

- a) Strengthening and repairing existing dams.*
- b) Remedial measures for foundation consolidation.*
- c) Increasing of flood discharge capacity.*
- d) Modification of operation to meet safety standards.*

**Mesures pour renforcer la sécurité
des barrages en service**

Objet

- a) Renforcements, réparations importantes.*
- b) Consolidation des fondations.*
- c) Augmentation de la capacité d'évacuation des crues.*
- d) Modification des conditions d'exploitation pour garantir la sécurité.*

QUESTION

59

TABLE OF CONTENTS
OF PAPERSTABLE DES MATIÈRES
DES RAPPORTS

	Page
R. 1. N. H. WADE, L. J. R. COURAGE, M. PILDYSH (<i>Canada</i>). Dam safety evaluation on a number of Canadian dams	1
R. 2. E. BIENER (<i>Fed. Rep. of Germany</i>). Rehabilitation of old gravity dams	21
R. 3. Z. SZLING (<i>Poland</i>). The durability of mineral-asphalt mixes in fastenings of earth-dams	35
R. 4. F. L. GIULIANI, A. PUJOL (<i>Argentina</i>). Seepage and slide downstream slope "Arroyito" dam, Argentina. Remedial measures	43
R. 5. A. RICOY DE OLIVEIRA, G. A. MELLIOS, M. N. SAAD (<i>Brazil</i>). Case histories of repairs of concrete surfaces subjected to water erosion	51
R. 6. A. RICOY DE OLIVEIRA, G. A. MELLIOS, R. J. CARDIA (<i>Brazil</i>). Erosion on the left wrap-around of José Ermírio de Moraes dam	73
R. 7. A. RICOY DE OLIVEIRA, C. R. DE MORAES LEME (<i>Brazil</i>). Adding 1 000 m ³ /s to Euclides da Cunha dam outflow	93
R. 8. D. VISCHER, G. TRUCCO (<i>Switzerland</i>). The remodelling of the spillway of Palagnedra	107
R. 9. R. SINNIGER, W. H. HAGER (<i>Switzerland</i>). Flood control by gated spillways	121
R. 10. B. H. SINSKE (<i>South Africa</i>). Gate operation — Flood control versus dam safety	151
R. 11. F. M. BUDWEG, F. MIGUEZ DE MELLO, J. MASAYOSHI GOTO, L. C. FRANCOLIN (<i>Brazil</i>). Rehabilitation of the Rasgao dam	171
R. 12. E. PLATE, W. BUCK, J. MEIER (<i>Fed. Rep. of Germany</i>). A simulation model for determining the probability of overtopping of dams	191
R. 13. N. MATSUMOTO, M. TAKAHASHI, F. SATO (<i>Japan</i>). Repairing the concrete facing of Minase rockfill dam	203
R. 14. J. A. BISCHOFF, T. C. MACDONALD, T. M. WILSON (<i>USA</i>). Rehabilitation of an old hydraulic fill dam for stability against earthquakes	227
R. 15. F. LUX III, D. L. HINCHLIFF (<i>USA</i>). Design and construction of labyrinth spillways	249
R. 16. R. P. SHARMA, B. T. SASAKI (<i>USA</i>). Rehabilitation of earthquake-shaken Pacoima arch dam	275

	Page
R. 17. G. BUREAU (<i>USA</i>). Seismic safety analysis and rehabilitation of dam inlet/outlet structures	297
R. 18. M. BILÍK, J. DVORÁČKOVÁ, J. KNOULICH, I. KYBAST, L. VOTRUBA (<i>Czechoslovakia</i>). Increasing the safety and reliability of dams during operation in Czechoslovakia	321
R. 19. A. DIACON, P. ANTOCI, I. BORDEA (<i>Roumanie</i>). Mesures pour améliorer la sécurité en exploitation et pour maintenir en service deux barrages de Roumanie	333
R. 20. W. C. LEGGE (<i>South Africa</i>). Modification of Vaal and Lerie dams to modern safety standards	343
R. 21. S. LASU (<i>Sweden</i>). Discharge safety in Swedish dams	359
R. 22. M. SERRANO TOVAR (<i>Spain</i>). Strengthening the Estangento dam	369
R. 23. E. AMMANN (<i>Suisse</i>). La transformation des barrages de Muslen et de List	381
R. 24. A. PINTO MAGALHÃES (<i>Portugal</i>). Labyrinth-weir spillways	395
R. 25. A. CORREIA DE SOUSA, M. PINHO DE MIRANDA, P. de PORCELLINIS, J. CATALAO (<i>Portugal</i>). La réparation du barrage de Paradela	409
R. 26. A. LENCASTRE (<i>Portugal</i>). Cross-jets : a solution for increasing discharge capacity of spillways	417
R. 27. R. OLIVEIRA, J. P. PEREIRA, M. P. DE MIRANDA, L. BRAGA DA CRUZ (<i>Portugal</i>). Consolidation of the foundation rock mass of Cambambe dam (<i>P. R. Angola</i>)	427
R. 28. O. P. DATTA, R. K. BHASIN, N. C. GUPTA (<i>India</i>). Repairs of Bhakra dam spillway apron	441
R. 29. SUDARJO (<i>Indonesia</i>). Modification of operation to meet safety standards	453
R. 30. F. NAGAO, T. TOYODA, M. MIZUNO (<i>Japan</i>). Construction of intake and outlet works associated with the redevelopment of existing dams	467
R. 31. M. ALONSO FRANCO, G. GOMEZ LAA, J. L. ROMERO HERNANDEZ (<i>Spain</i>). Updating of Spanish dams from a safety standpoint	493
R. 32. A. ALVAREZ, E. HERRERO, J. M. BUIL (<i>Spain</i>). Strengthening of some existing dams	505
R. 33. W. HAUG, K. DITTER, W. D. GEISELER (<i>Fed. Rep. of Germany</i>). Two examples for the regeneration of cement concrete and asphaltic concrete linings of water storage reservoirs by means of asphaltic concrete	527

	Page
R. 34. B. HEDLUND, G. B. MÅRTENSSON (<i>Sweden</i>). Measures for the safety of dams at Harsprånget and Ligga in connection with the extension of capacity in the river Lule Älv	541
R. 35. R. KJELLBERG, U. NORSTEDT, H. FAGERSTRÖM (<i>Sweden</i>). Leakage in and reconstruction of the Juktan earth and rockfill dams	553
R. 36. T. HOFF, K. Y. NILSEN (<i>Norway</i>). Erosion and leakage problems on some Norwegian dams	573
R. 37. A. PEPPER, D. ANDERSON (<i>Australia</i>). Chichester dam rehabilitation	587
R. 38. P. J. CUMMINS, B. R. SMITH, R. C. EVANS (<i>Australia</i>). Rehabilitation of Goulburn weir foundations and superstructures	603
R. 39. F. CASTRO, E. GARCES (<i>Chile</i>). Cement-bentonite cut off for reconditioning Bullileo earth dam	619
R. 40. H. WELLACHER, P. TSCHERNUTTER (<i>Austria</i>). Repair of a high-altitude rockfill dam with an upstream asphalt concrete membrane	633
R. 41. W. HONGEN (<i>China</i>). Analysis of the in-situ observation data on the fracturing grouting in the Huang Qian dam	647
R. 42. SHANGGUAN NENG, ZU ZHISHENG (<i>China</i>). Strengthening of the interbedded layers in Shuangpai dam foundation during operation	659
R. 43. R. URBISTONDO, L. YGES (<i>Spain</i>). Fragmentation of the El Atazar dam foundation rock after 14 years in operation	673
R. 44. E. VALLARINO, A. DEL CAMPO (<i>Spain</i>). Conditioning dams in service for evacuating foreseeable flood flows	693
R. 45. A. LEBRETON, P. MALIVERNEY, D. BROUSSE, M. LINO, M. PACCARD (<i>France</i>). Renforcement de la structure de certains barrages français. Cas des barrages de Grosbois I et II, de Joux et de la Beaume	703
R. 46. J. COMBELLES, A. GOUBET, N. LLOPIS, M. PACCARD (<i>France</i>). Mesure destinées à améliorer la sécurité des ouvrages hydrauliques des barrages	725
R. 47. E. MORENO, J. J. VAZQUEZ (<i>Mexico</i>). El Infiernillo dam. Operation, damage and repair of the spillway tunnels	747
R. 48. D. BULCKAEN, C. JARRIN (<i>Belgium</i>). A real time flood forecasting model as a help in the operation of the Agoyan dam in Ecuador	763
R. 49. GROUP OF THE SWISS NATIONAL COMMITTEE (<i>Switzerland</i>). Maintenance and rehabilitation connected with Swiss dams over fifty years old	781

	Page
R. 50. G. IVANOV, B. LAZARIĆ (<i>Yugoslavia</i>). Tracing tests for evaluation of the grouting curtain condition under "Spilje" hydroelectric powerplant dam	799
R. 51. L. VAJDA, J. MUSKATIROVIC (<i>Yugoslavia</i>). Some possibilities for increasing the discharge capacity	815
R. 52. V. SIMEONOVA (<i>Bulgaria</i>). Overflow capacity of energy-dissipators of dams	831
R. 53. J. E. CASTILLA, P. COLINA (<i>Mexico</i>). Santa Rosa arch dam reinforcement of the left bank	843
R. 54. R. KUUSINIEMI (<i>Finland</i>). Improving the frost protection in the earth dams of the Finnish National Board of Waters	853
R. 55. J. H. FLEMMING, D. T. ROSSINGTON (<i>Great Britain</i>). Repair of Greenbooth dam following localised settlement in the crest	875
R. 56. P. G. MACKEY (<i>Great Britain</i>). Rehabilitation to meet reservoir safety and flood criteria	899
R. 57. L. MIKHAILOV, V. SEMENKOV, L. SMIRNOV (<i>USSR</i>). Methods of increase of discharge capacity of hydroelectric sche- mes during floods on large rives in the USSR	921
General Report/Rapport Général	929