

Grindelwald, Switzerland, 26-28 April 1993

SUPPLEMENTARY VOLUME

Special lecture on

THE PERUĆA DAM, CROATIA

Sponsored by

HRVATSKA ELEKTROPRIVREDA - CROATIAN NATIONAL ELECTRICITY



elektroprojekt Consulting Engineers Ltd.



Edited by Dr. J. Rupčić and T. Megla

© Copyright: elektroprojekt Ltd. 1993

37 Avenija Vukovar 41000 ZAGREB, CROATIA

Fax: (38 41) 53 05 04 Tel: (38 41) 62 51 11

SUPPLEMENTARY VOLUME - INTERNATIONAL WORKSHOP ON DAM SAFETY EVALUATION, 1993

INDEX: SPECIAL LECTURE - THE PERUĆA DAM, CROATIA -

- 1 T Megla A reason for additional considerations on dam safety
- 5 J Rupčić An overview of the Peruća reservoir and its structures
- 13 M Petričec Climatological and hydrological data on the catchment area of the Cetina river and the Peruća reservoir
- 21 Z Sever Effects that would have arisen had the Peruća dam been destroyed
- 31 J Macan Chronology of events on the Peruća dam from occupation till mining
- 35 M Vilović The Peruća dam damage after explosion
- 41 V Kuk, D Herak and M Herak Seismological investigations after the Peruća dam explosion of January 28, 1993
- 47 V Dadić and B Grbec Measurements of the water flow and temperature in the Peruća reservoir
- 53 A Salković and D Dujmić Geophysical investigation at the Peruća dam
- 57 E Nonveiller The Peruća dam after the explosion
- 67 P Grgić Consequences of the Peruća dam mining as regards electricity supply to the Dalmatia region